

HAZARDS IDENTIFIED WITH THIS TASK

HAZARD	SEVERITY	EXPOSURE	RATING	HAZARD	SEVERITY	EXPOSURE	RATING
Lifting Heavy Loads	3	2	6	Lifting Blocks in use	3	1	3
Trapped by conveyor	3	2	6	Locks in use	3	1	3
Damage hands – trapping	3	2	6	Wear gloves	3	1	3
Damage hands – Stanley knife	3	2	6	Wear gloves	3	1	3
Fumes from vulcanise solution	3	1	3	Dust masks used	3	1	3

COSHH REQUIREMENTS	PLENTY OF VENTILATION NO NAKED FLAMES BREATHING APPARATUS WHEN REQUIRED
---------------------------	--