

RISK ASSESSMENT

RISKS

MINIMISED BY

Lifting heavy objects	Correct lifting gear
Trapped by conveyor	Locks in use/flash tape area off
Cuts from knife	Wearing suitable gloves
Trap/Bruises injury to hands and feet	Wearing suitable gloves and safety boots
Slips, trips and falls	Keep work area clean and tidy
Pulling belt on	Correct ropes, pulley wheels, slings, chains to be used
Working at height	Use only designated walkways and platforms
Falling objects	Wear hard hat, eye protection and flash tape area off
Weather	During bad weather use sheeted areas, sheeting and be extra vigilant
Fire	Minimise waste and ensure COSHH regulations are complied with
Glue	COSHH regulations are complied to
Electricity	No cable exposed to water. Adequate earth leakage protection is available
Moving machinery	Area is flash taped off
Electric power tools	PAT tested and in date. Also daily inspection are carried out
Grinding	Protective eye protection to be worn and gloves