

## **METHOD STATEMENT FOR GRINDING**

1. Wearing correct PPE i.e. gloves and eye protection.
2. Check to ensure that grinder is in good working order.
3. Ensure disk is correct for job and secure.
4. Ensure that no persons are in the vicinity.
5. Proceed to grind step lines.