

**METHOD STATEMENT AND RISK ASSESSMENT FOR**

**USE OF ELECTRIC SPANNERS**

**SITE:**

**CONVEYORS:**

Wearing standard PPE of: overalls, safety boots, hard hat, appropriate gloves and eye protection.

Ensure that sockets used are in good condition.

Ensure plugs and sockets are in good order.

Fix socket securely to the tool.

Use to tighten and loosen fixings or with correct attachments.

**RISKS**

**MINIMISED BY**

Flying debris

Eye protection

Trap/bruises injury to hands and feet.

Wearing suitable gloves and boots.

Electric shock

Equipment tested